

# MANAGEMENT SYSTEM CERTIFICATE

Certificate No:  
19046-2008-AQ-USA-ANAB

Initial certification date:  
15 January 2008

Valid:  
15 January 2017 - 15 January 2020

This is to certify that the management system of

## **AerSale, Inc.**

511 East Challenger Street, Roswell, NM, 88203, USA  
and the sites as mentioned in the appendix accompanying this certificate

has been found to conform to the Quality Management System standard:  
**ISO 9001:2015**

This certificate is valid for the following scope:  
**The Distribution of Aerospace Components**

Place and date:  
Katy, TX, 15 January 2017



For the issuing office:  
DNV GL – Business Assurance  
1400 Ravello Drive, Katy, TX, 77449-5164,  
USA

**John Stefan**  
Management Representative

Certificate No: 19046-2008-AQ-USA-ANAB  
 Place and date: Katy, TX, 15 January 2017

## Appendix to Certificate

### AerSale, Inc.

Locations included in the certification are as follows:

Site Name	Site Address	Site Scope
AerSale, Inc.	511 East Challenger Street, Roswell, NM, 88203, USA	The Distribution of Aerospace Components
Warehouse 1081	80 West Earl Cummings Loop, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)
Warehouse 112	56 G Street, Roswell, NM, 88203, USA	Outsourced Sales Orders (Pick Ticket generation), Parts Material Inspection, Distribution (planning, warehouse/inventory, picking, receiving, shipping.)
Warehouse 115	46B East Martin Street, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)
Warehouse 118	48 East Martin Street, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)
Warehouse 240	42 East Earl Cummings Loop, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)
Warehouse 520	514 East Challenger Street, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)
Warehouse 92	39 Jennifer Lane, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)
Warehouse 93	1 East Earl Cummings Loop, Roswell, NM, 88203, USA	Parts Material Inspection, Distribution (warehouse/inventory, picking.)